




Nº 135 SERVICE BULLETIN



Joe Blackwell
Director, Parts Sales &
Technical Support

Susan White
Parts Sales
Manager

Patty Schraps
Parts Stockroom
Manager

Chas Siddiqi
Technical Support
Engineer

Jay Alfer
Technical Support Doc.
Administrator

TO: Parts & Service Managers

DATE: May 1, 2002

SUBJ: OPTIONAL  Ramp Butyrate Fix Kit (SPI: 502-5012-00)

Symptom:

Some **playfield shots** (from the flipper) into the *open Bank Door*, up the Center Ramp, tend to "loft" and hit the Center Ramp Entrance Gate Bracket *or* may lodge behind the "Free Parking Sign." If it hits the Gate Bracket, it causes the ball to be returned down the ramp, unable to complete the shot.


Explanation:

Locations with a *higher than normal* Line Voltage, may see lofting due to the *increased strength* of the Flippers. If you're experiencing the above symptom, the following **OPTIONAL Kit** may be purchased through your distributor.

Solution:

Attach the new *Clear Plastic (Butyrate) Piece* over the ramps as shown in the graphic below. This *Clear Plastic Piece* is included in the **OPTIONAL MONOPOLY® RAMP BUTYRATE FIX KIT** (SPI: 502-5012-00), along with this **Service Bulletin 135** (SPI: 756-5012-00), #6 X 1/2" PTH A Screws (Qty. 2) (SPI: 237-5809-00) and *Clear Plastic (Butyrate) Piece* (Qty. 1) (SPI: 830-5995-00).

Note: This new piece will be included **in any future orders** of the **Monopoly® Clear Plastic Set** (830-5987-XX).



Step 1: Line up the new Clear Plastic (Butyrate) as shown and mark the 2 holes. Using a 3/32" Drill Bit, drill the 2 holes.

Step 2: Using the 2 screws, affix plastic.

Please phone or eMail with any questions or comments at the below numbers or address.



• 2020 Janice Ave • Melrose Park, IL 60160 • Tel 708-345-7700 (Option 1) • Toll-Free (USA/Canada) 1-800-542-5377 • Fax 708-345-7889 •

Received via Fax? For a better copy, download from our website: www.sternpinball.com/bulletins.htm

S.B. Nº 135
Page 1 of 1

Want Service Bulletins by eMail? Request by eMail: parts.service@sternpinball.com
Instruction Sheet SPI Part Nº: 756-5012-00