

**Service Bulletin #42**

To: Service Managers
From: Data East Pinball Service Department
Date: June 22, 1993
Subject: Left-Right motor on Jurassic Park Fails prematurely.

Symptom: The Left-Right motor fails prematurely, or struggles to move the head left and right.

Cause: Damage to the gearbox, due to excessive speed of the mechanism. (The motor operates one of the switches used to stop it's rotation and due to wide variations of the motor speed, over travels and strikes the mechanical stop.)

Cure: To prevent shock to this motor, use the attached diagram to adjust the left and right limit switches and change the program to version 5.00 as supplied in the kit. The new program provides a more intelligent speed control to help slow it down prior to the limit switch closure.

Note- All of these changes have occurred by game Serial # 87177.

If you have any further questions, please contact Jim or Arnie at 800-542-5377.