

№ 125



Joe Blackwell Director, Parts Sales & Technical Support Susan White Parts Sales Manager

Tashia Miles Customer Service Representative Patty Schraps Parts Stockroom Manager

R421 M19 P422

Jim Thornton Technical Support Engineer

10

Chas Siddigi Technical Support Engineer Jay Alfer Technical Support Doc. Administrator

Parts & Service Managers

DATE: April 19, 2001

SUBJ: Quick Tip for Display Troubleshooting:

U201 White Star Board System™

Sumptom:

The DOT DISPLAY is not functioning in Game *Mode*, however, game functions are **OK**. Upon Power-Up, the Display shows the "Display Version of Software" then goes BLANK.

Problem:

U201 Failed. U201 is a 74HCT273 Data Latch (see the CPU Sound Bd. pictorial, lower right).

Solution:

Replace U201.

Troubleshooting Tips:

First check that all the Ribbon Cables & Connecters are secure.

Depress the Begin Test Button (inside the Coin Door, #3 Black Button) to enter Diagnostics (Note: You do not need a working display to perform this test). Though you will not see any display graphics you have just entered the Portals Service Menu; by actuating the Flipper Buttons you will be forcing a display call. If this is performed with a working Display, you will see that you are moving an icon across the screen. A state change at the outputs of **U201** will occur if **U201** is good. Due to the slow speed the ouputs toggle at, a Multimeter can be used to check the outputs of U201 at Pins 2, 5, 6, 9, 12, 15, 16 & 19.

In *Normal Operation*, the **OUTPUTS** are typically in a high or low state toggling 0 volt to 5 volts as a byte of data is being latched to the ouput. This byte of data can also be referred to as a Display *Call.* This would indicate the latch is **operating** correctly.

If U201 has failed, the OUTPUTS may have one or more of the following conditions:

- erratic or oscillating signal
- have no clean 0v to 5v transistions (e.g. 3.2v)
- one or more bits stuck high or low

Continued on the next page.


1483 PH16 BAT1 **J**P417 R407 R408 R485 MIS C499 C491 405 402 P418 406 VBATT U209 U212 U210 **74LS** U209 6264/MS62256 L201 SW200 GND1 74HC245 L200 **u201** R302 74LS374 R217 74LS374 U201 74HCT74 . R219 R218 R295 R220 R221 R222 R223 R242 74HC245 R243 R224 E21 R225 R226 C218 R231 I_{R227} R228 (-) CN'

• 2020 Janice Ave • Melrose Park, IL 60160 • Tel 708-345-7700 (Option 1) • Toll-Free (USA/Canada) 1-800-542-5377 • Fax 708-345-7889 •

Excerpt from CPU/Sound Board Theory of Operation (re: Plasma Interface):

Plasma Interface: The data path for communication to and from the Plasma Controller Board is 8 bits wide. There are separate *Input* and *Output Busses*. The *Input Bus* from the Plasma Controller to the CPU/Sound Board comes in on CN8 [PLASMA CONTROL]-Pins 3-10 and is fed into U200 for input to the CPU's *Data Bus*. Data going out to the controller comes from the CPU's *Data Bus* through U201 and onto CN8-Pins 11-18. Status back from the Plasma Controller comes in on CN8-Pins 22-26 and is fed into U202 for input to the CPU's *Data Bus*. Two control signals that go out to the Plasma Controller are PRES [PLASMA RESET] and CN8-Pin 19 [PSTB - Plasma Strobe]. The Plasma Reset is software controllable through U216/B and also has a test point "Plasma Reset". The *Plasma Strobe Signal* to the controller is generated from U216/A and is *used to latch data* into the Plasma Controller.

CPU/Sound Board Schematic (Sheet 3 of 3)



Please phone or eMail with any questions or comments at the below numbers or address.

^{• 2020} Janice Avenue • Melrose Park, IL 60160 • Tel 708-345-7700 or Toll-Free (USA/Canada) 1-800-542-5377 • Fax 708-345-7889 •