



DATA EAST PINBALL, INC.

## Service Bulletin #018

To: Service Manager  
Date: June 12, 1989  
Game: Playboy 35th ANNIVERSARY  
Subject: Program Revision

---

Symptom: Intermittently the laser kick coil kicks too late when a ball passes out the left drain quickly. This is an irritant to a player when he or she sees the coil kick and it misses the ball.

Problem: The response time between the switch closure to coil kicking is too long.

Solution: Enclosed is a set of CPU board EPROMS (Version A02-3) that corrects this problem. It is recommended that you install them in the sample games you have received. If you have any questions please call Arnie or me at 1-800-KICKERS (1-800-542-5377).

Pete Gustafson  
Field Service Manager  
Data East Pinball, Inc.