



**Service Bulletin #40**

To: Service Managers  
From: Data East Pinball Service Department  
Date: June 22, 1993  
Subject: Weak kick on Dino Saucer Eject

**Symptom:** The saucer located in front of the dinosaur assembly kicks weakly.

**Cause:** Poor spotting of the assembly, and the possibility of a mismatched spring.

**Cure:** Use the spotting diagram provided to insure that the screws are in the proper locations on the playfield. Change the extension spring with the one we are providing in the kit.

Note- All of these changes have occurred by game Serial # 87177.

If you have any further questions, please contact Jim or Arnie at 800-542-5377.