

**Service Bulletin #43**

To: Service Managers  
From: Data East Pinball Service Department  
Date: June 22, 1993  
Subject: Failure of switch #37 (Center Scoop) on Jurassic Park Pinball.

**Symptom:**Center scoop switch fails, preventing features from being acquired by shooting the ball into the control room.

**Cause:**Broken Diode on center scoop switch.

**Cure:** Replace the damaged diode. To prevent shock damage to the diode, apply a silicon rubber compound to the points where the diode is formed to absorb the impact.

Note- All of these changes have occurred by game Serial # 87390.

If you have any further questions, please contact Jim or Arnie at 800-542-5377.