



**SERVICE BULLETIN 01
(Reprint)**

FROM: Pete Gustafson, Field Service Mgr.
TO: Service Managers
DATE: April 12, 1988
RE: Secret Service - Playfield Ball Trap

Problem: Ball gets stuck on top of clear plastic above white house (see Fig. 1).

Solution: Call Field Service at 1-800-KICKERS (1-800-542-5377) and request a Secret Service ball trap modification kit. The kit consists of the following parts:

<u>Quantity</u>	<u>Item</u>	<u>Part Number</u>
1	Spacer	254-5000-01
1	Screw	237-5506-00
1	Flat Washer	242-5005-00
1	Star Washer	246-5000-00
1	Nut	240-5004-00
1	Installation Instructions (No P/N)	

Note 1: This only affects a few Secret Service games. The majority of games had this modification installed at the factory.

Note 2: Please have the game serial number available when calling for this modification.