


# Service Bulletin N<sup>o</sup> 109



<b>Joe Blackwell</b> Director, Parts Sales & Technical Support	<b>Susan Molitor</b> Parts Sales Manager	<b>Patty Schraps</b> Parts Stockroom Manager	<b>Eric Winston</b> Technical Support Engineer	<b>Doug Lemons</b> Technical Support Engineer	<b>Linda Garza</b> Customer Service Representative	<b>Jay Alfer</b> Technical Support Doc. Administrator
--	--	--	--	---	--	---

**TO:** Parts & Service Managers



**DATE:** September 30, 1998

**SUBJ:** GODZILLA PINBALL GAME MANUAL ADDENDUM: Flipper Coils

**Explanation:**

After further field testing, our Engineering Staff had determined stronger Flipper Coils would greatly enhance the play and feel of the Godzilla Pinball. Therefore, the Left & Right Flipper Coils were changed in Production from 23-1100, Orange (090-5030-00T) **TO** 22-1080, Yellow-Green (090-5032-00T). This will also change the Assembly Part N<sup>o</sup> for both Flippers 500-5944-14 **TO** 500-5944-12 (Left) and 500-5944-04 **TO** 500-5944-02 (Right). If you have an early production game and have determined you have the "Orange" wrap Flipper Coils, please call Technical Support for Assistance.

The following pages in the **GODZILLA GAME MANUAL** have changed (due to the Flipper Coils). A copy of this Service Bulletin will be included with the Game Manual for pinballs remaining in the factory. Please ensure your Game Manual has this copy. The below Addendum Table annotates all areas in the manual where the now incorrect Flipper Coil is referenced.

**Addendum:**

<b>Page:</b> DR. ⑥ <b>Coils Detailed Chart Table</b> Item #15 <b>From:</b> 23-1100 090-5030-00T <b>TO:</b> 22-1080 090-5032-00T	<b>Page:</b> DR. ⑥ <b>Coils Detailed Chart Table</b> Item #16 <b>From:</b> 23-1100 090-5030-00T <b>TO:</b> 22-1080 090-5032-00T
<b>Page:</b> ii <b>Table of Contents</b> "Page 72" <b>From:</b> (Left) ...500-5944-14 <b>TO:</b> (Left) ...500-5944-12	<b>Page:</b> ii <b>Table of Contents</b> "Page 73" <b>From:</b> (Right) ...500-5944-04 <b>TO:</b> (Right) ...500-5944-02
<b>Page:</b> 22 <b>Coil &amp; Flash Lamp Desc.</b> "Coil 15" <b>From:</b> (23-1100) <b>TO:</b> (22-1080)	<b>Page:</b> 22 <b>Coil &amp; Flash Lamp Desc.</b> "Coil 16" <b>From:</b> (23-1100) <b>TO:</b> (22-1080)
<b>Page:</b> 24 <b>Coils Detailed Chart Table</b> Item #15 <b>From:</b> 23-1100 090-5030-00T <b>TO:</b> 22-1080 090-5032-00T	<b>Page:</b> 24 <b>Coils Detailed Chart Table</b> Item #16 <b>From:</b> 23-1100 090-5030-00T <b>TO:</b> 22-1080 090-5032-00T
<b>Page:</b> 25 <b>...Detailed Wiring Diagram</b> Q15, J9 Pin-8 <b>From:</b> 23-100 <b>TO:</b> 22-1080	<b>Page:</b> 25 <b>...Detailed Wiring Diagram</b> Q16, J9 Pin-9 <b>From:</b> 23-100 <b>TO:</b> 22-1080
<b>Page:</b> 72 <b>Flipper (Left) Assembly, 500-5944-14</b> <b>From:</b> (Left) ...500-5944-14 <b>TO:</b> (Left) ...500-5944-12	<b>Page:</b> 73 <b>Flipper (Right) Assembly, 500-5944-04</b> <b>From:</b> (Right) ...500-5944-14 <b>TO:</b> (Right) ...500-5944-12
<b>Page:</b> 72 <b>Assembly Parts Table</b> Item #16 <b>From:</b> 23-1100 090-5030-00T <b>TO:</b> 22-1080 090-5032-00T	<b>Page:</b> 73 <b>Assembly Parts Table</b> Item #16 <b>From:</b> 23-1100 090-5030-00T <b>TO:</b> 22-1080 090-5032-00T
<b>Page:</b> 80 <b>Coils Detailed Chart Table</b> Item #15 <b>From:</b> 23-1100 090-5030-00T <b>TO:</b> 22-1080 090-5032-00T	<b>Page:</b> 80 <b>Coils Detailed Chart Table</b> Item #16 <b>From:</b> 23-1100 090-5030-00T <b>TO:</b> 22-1080 090-5032-00T
<b>Page:</b> 82 <b>...Detailed Wiring Diagram</b> Q15, J9 Pin-8 <b>From:</b> 23-100 <b>TO:</b> 22-1080	<b>Page:</b> 82 <b>...Detailed Wiring Diagram</b> Q16, J9 Pin-9 <b>From:</b> 23-100 <b>TO:</b> 22-1080
<b>Page:</b> 86 <b>2-Flipper Circuit Wiring...</b> Left Flipper <b>From:</b> 23-100 <b>TO:</b> 22-1080	<b>Page:</b> 86 <b>2-Flipper Circuit Wiring...</b> Right Flipper <b>From:</b> 23-100 <b>TO:</b> 22-1080
<b>Page:</b> 119 <b>Appendix E... Godzilla Lower Flipper Left</b> <b>From:</b> -5030- 23-1100 ORG <b>TO:</b> -5032- 22-1080 YEL-GRN	<b>Page:</b> 119 <b>Appendix E... Godzilla Lower Flipper Right</b> <b>From:</b> -5030- 23-1100 ORG <b>TO:</b> SAME

Any questions or concerns please contact Technical Support at the below numbers.

• 1990 Janice Avenue • Melrose Park, IL 60160 • Tel 708-345-7700 or Toll-Free (USA/Canada) 1-800-542-5377 • Fax 708-345-7889 •