



DATA EAST PINBALL, INC.

## Service Bulletin #017

To: Service Manager  
Date: 5-26-89  
Subject: Ball Time and Free Play Percentage  
Game: Playboy 35th ANNIVERSARY

---

Problem: After reviewing the audits from some of the first built games we are finding that the ball time and free percentage has been averaging below the factory recommended settings.

\*\*Factory recommended ball time is 45 to 55 seconds.\*\*  
\*\*Factory free percentage is 22 to 26 percent.\*\*

Solution: For the free percentage set the high score from 3,000,000 to 2,400,000. (The new program A02-3 will make the high score change automatically.)

For the ball time replace the right drain adjustable post and rubber ring with a jeweled post and rubber ring (see attached picture). Position it to the highest of the three positions. If the ball time is extremely low (25 sec. or less) it can be increased by removing the steel mini post that is mounted above and between the right flipper feed and right drain lanes.

Pete Gustafson  
Field Service Manager  
Data East Pinball, Inc.