



## Service Bulletin #21

To: Service Manager  
From: Data East Pinball Field Service  
Date: December 5, 1989  
Subject: Flipper Links on ABC Monday Night Football

---

Symptom: Flipper links break after approximately 7 to 10 days.

Problem: The green plastic used to make the link was allowed to get too hot in its mold which caused it to become brittle. Only a very small percentage of the links were over heated however, in order to distinguish a good link from a potentially bad one we are changing the color of the link from green to blue.

Solution: We are providing you with 20 blue flipper links at no charge. if you have any questions regarding these links please call Pete or Arnie at 1-800-KICKERS (1-800-542-5377).

*Pete*      *Arnie*

Pete and Arnie  
Data East Pinball, Inc.  
Field Service Department