



## Service Bulletin #30

To: Service Manager  
From: Data East Pinball Service Department  
Date: 19 Sept. 1991  
Subject: BATMAN Shooter Lane Switch

---

Symptom: Shooter lane switch get's stuck on top of playfield.

Problem: The ball kicks into the shooter lane but if the switch is not adjusted properly the ball will fall behind it and the automatic kicker thrusts the ball forward, it will bend and or break the shooter switch.

Solution: Replace shooter switch. Contact Data East Pinball at 1-800-542-5377 with your games serial number and we will send you a replacement at no charge.